



**Knife edges will not build completely. This is caused by the beam diameter and limitations of the build process. This can cause significant differences between design intent versus prototype end result.**

